

ASSEMBLY INSTRUCTION

7013-CP1702-B-1461



A x8
Spec: $\phi 10 \times 10$



A1 x4
Spec: $\phi 7 \times L30$



A2 x4
Spec: $\phi 15 \times H12$



B x4
Spec: $M8 \times L95$




C x4
Spec:



D x4
Spec: M8



E x4
Spec: $\phi 38$



I x1
Spec: 5#



K x1
Spec: 14#



R x19
Spec: $\phi 8 \times \phi 18$



N x3
Spec: $5/16 \times L60$



F x16
Spec: $M6 \times L5$



G x1
Spec: 10g



H x3
Spec: L205



FIG.
1




FIG.
2




FIG.
3




FIG.
4




FIG.
5

